

Message Text

CONFIDENTIAL

PAGE 01 PEKING 01051 180323Z
ACTION SY-05

INFO OCT-01 EA-10 ISO-00 SYE-00 /016 W
-----052343 180337Z /64

P R 180244Z APR 78
FM USLO PEKING
TO AMEMBASSY NEW DELHI PRIORITY
INFO SECSTATE WASHDC 443
AMCONSUL HONG KONG
AMEMBASSY TOKYO

C O N F I D E N T I A L PEKING 1051

DEPT FOR SY/T

NEW DELHI FOR TSO CAMP

HONG KONG FOR RTC

TOKYO FOR TSO

E.O. 11652: GDS
TAGS: ASEC
SUBJ: AUTO-SCAN PROBLEMS AT USLO

1. EXPERIENCING DIFFICULTY IN ACTIVATING AUTOSCAN.
2. REPAIRED BOARD WITH DAMAGED CAPACITORS AND SYSTEM
WORKED FINE FOR TWO DAYS. WHILE LETTING THE SYSTEM
SCAN BANDS 1 AND 2 ON 4/17, NOTICED THAT AFTER A FEW
HOURS, THE MD-104 BEGAN NOT LOCKING ON ANY SIGNALS.
PROBLEM MAY BE WITH PRINTER INTERFACE AND SCAN MODE
BOARD IN COUPLER, AS EVERYTHING ELSE APPEARS TO WORK
EXCEPT PRINTER.
3. THE PRINTER SUDDENLY STOPPED WORKING IN CERTAIN
AREAS. THE PAPER ADVANCE FUNCTION DOES NOT WORK AT
CONFIDENTIAL

CONFIDENTIAL

PAGE 02 PEKING 01051 180323Z

ALL - THE SWITCH IS FUNCTIONING PROPERLY.
ANOTHER PROBLEM IS WHEN THE UNIT IS IN THE PRINT MODE.
THE FIRST LINE IS ALWAYS OVERWRITTEN ONCE AND THEN
CONTINUES CORRECTLY.

4. POST WOULD APPRECIATE TDY VISIT BY TSO CAMP AS
SOON AS HIS SCHEDULE PERMITS. PLEASE ADVISE.

5. FOR SY/T: WE ARE UNSURE HOW TO FUND THE TDY TRIP
WHICH COULD LAST TWO WEEKS. CAN SY/T PROVIDE FUNDING?
WOODCOCK

CONFIDENTIAL

NNN

Message Attributes

Automatic Decaptioning: X
Capture Date: 01 jan 1994
Channel Indicators: n/a
Current Classification: UNCLASSIFIED
Concepts: n/a
Control Number: n/a
Copy: SINGLE
Draft Date: 18 apr 1978
Decaption Date: 01 jan 1960
Decaption Note:
Disposition Action: RELEASED
Disposition Approved on Date:
Disposition Case Number: n/a
Disposition Comment: 25 YEAR REVIEW
Disposition Date: 20 Mar 2014
Disposition Event:
Disposition History: n/a
Disposition Reason:
Disposition Remarks:
Document Number: 1978PEKING01051
Document Source: CORE
Document Unique ID: 00
Drafter: n/a
Enclosure: n/a
Executive Order: GS
Errors: N/A
Expiration:
Film Number: D780165-0231
Format: TEL
From: PEKING
Handling Restrictions: n/a
Image Path:
ISecure: 1
Legacy Key: link1978/newtext/t19780445/aaaabluj.tel
Line Count: 66
Litigation Code IDs:
Litigation Codes:
Litigation History:
Locator: TEXT ON-LINE, ON MICROFILM
Message ID: a18c07ac-c288-dd11-92da-001cc4696bcc
Office: ACTION SY
Original Classification: CONFIDENTIAL
Original Handling Restrictions: n/a
Original Previous Classification: n/a
Original Previous Handling Restrictions: n/a
Page Count: 2
Previous Channel Indicators: n/a
Previous Classification: CONFIDENTIAL
Previous Handling Restrictions: n/a
Reference: n/a
Retention: 0
Review Action: RELEASED, APPROVED
Review Content Flags:
Review Date: 02 may 2005
Review Event:
Review Exemptions: n/a
Review Media Identifier:
Review Release Date: n/a
Review Release Event: n/a
Review Transfer Date:
Review Withdrawn Fields: n/a
SAS ID: 2932974
Secure: OPEN
Status: NATIVE
Subject: AUTO-SCAN PROBLEMS AT USLO
TAGS: ASEC
To: NEW DELHI
Type: TE
vdkgvwkey: odb://SAS/SAS.dbo.SAS_Docs/a18c07ac-c288-dd11-92da-001cc4696bcc
Review Markings:
Sheryl P. Walter
Declassified/Released
US Department of State
EO Systematic Review
20 Mar 2014
Markings: Sheryl P. Walter Declassified/Released US Department of State EO Systematic Review 20 Mar 2014